

How to remove tar

1. 2. 3. 4. 5.
Spray On - Soak - Scrub - Spray on - Wipe Dry

1. Spray SafeSolv on the tar covered area
2. Let soak for 1-5 minutes
3. Scrub the area with the Aero Scrubber
4. Re-Spray the area with SafeSolv
5. Wipe the area with a soft towel
6. Repeat until all tar is completely removed
7. Clean the area with Wash Wax ALL (Blue)

NOTE:

SafeSolv is a non-toxic biodegradable way to remove tar.